



CNC-DRIVEN COORDINATE WELDING PLANT

>>THE TASK...

Welding of 4-sided nuts to a seat belt bracket



AUTOMOTIVE

...OUR SOLUTION AT A GLANCE<<

CNC COORDINATE WELDING PLANT

Plant with 2 operator workplaces, where the work-
place carriers are assembled alternatingly.

In the other position the welding machine travels
through the welding positions along the X & Y axes.

Nuts are positioned automatically and the workpie-
ces welded in the individual tablet position.